


# Closing loop cable

1. Use the same procedure as described in the outlet cable, regarding treatment of the outer casing and the insulation. Cut the cables to an appropriate length, so they can reach each other, without touching the steel pipe. Crimp the two cables together with the crimp cable connection.

2. Place the end-cap in position and shrink it with a gas burner. (see 7.11)

**NOTE: Take care that the heat does not damage the cable.**



**biosteel a/s**

Algade 35, Grønbjerg · DK-6971 Spjald, Denmark  
+45 4027 8099 · info@biosteel.dk · [www.biosteel.dk](http://www.biosteel.dk)